Manufactured Home Foundation Detail

Regular Frame

Anchors must be counter sunk and not protrude above sill plate



